

General Certificate of CPSIA Compliance

Customer & Ship To Address:

ROCKRIDGE PARK
27180 SUMMERWINDS RD.
MORENO VALLEY, CA 92553
Order Number:605981

The following product models are covered by this certificate:

7145019	DECK TRIANGLE ATTACHES TO 3 POSTS MT II
7145029	DECK SQUARE ATTACHES TO 4 POSTS
71453639	DECK CS HEXAGON 3' DECK FOR ROOF MT II
71453659	DECK CS HEXAGON 5' DECK FOR ROOF MT II
714551	POST 5"OD X 106" 2'6" DECKS OR LESS
714552	POST 5"OD X 136" 3'-5' DECKS
714553	POST 5"OD X 160" 5'6"-6'6" DECKS
71457218	POST 5" OD X 18" EXTENSION W/HARDWARE
714573	POST 5" OD X 168" FOR ROOF 3'6"-5' DECK
714700	SLIDE 5' SIDE-BY-SIDE W/CANOPY 3' DECK
7147135B	PANEL DOOR BELOW DECK ONLY
7147147B	PANEL PILOT W/O WINDOW 2 WHEELS BELOW DK
7147156B	PANEL BUS STOP BENCH BELOW DECK
714720	CLIMBER OUTRIGGER 5' & 6'6" DECK
714733	SIGN WELCOME AGES 5-12 FREE STANDING
7147332	SIGN WELCOME AGES 2-12 FREE STANDING
7147555	CLIMBER HONEYCOMB 5' DECK
71475734	CLIMBING WALL SLOPED 45 DEG 3' OR 4' DK
71475959	SLIDE TYPHOON 9'4" 630 DEG 5' DK MT II
7147743	BONGO STEPS TO 3' DECK
71477431	BONGO STEPS TO 3' DECK W/HAND SUPPORTS
714784	TORNADO DECK MOUNTED
714786	BONGO JUNGLE CLIMBER 10' BETWEEN 3' DKS
7148153	LADDER VERTICAL 3' DECK
714816	WALL ENCLOSURE
71485139	TRANSFER POINT SQUARE 3' DECK
7148624	ROOF FOR 4' SQUARE DECK, PERF STEEL
7148626	ROOF FOR HEXAGON DECK, PERF STEEL
7148626c	CUPOLA TOP PERF STEEL FOR HEX ROOF
714876B	PANEL CRAWL THRU BELOW DECK
71495949	STAIR ADA 2' RISE BTWN 4' DK CLOSE RAIL
714968	CLIMBER CURVED LOOP 3' DECK
7149748	CLIMBER WIGGLY WORM 5', 6'6" OR 8' DECK
71499269	KIDS' PERCH W/WHEEL MTII
714994	FUN FONES GROUND TO GROUND
714999	INSTALLATION KIT KC

Each of these products is in compliance with the following sections of the

Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101 Lead Paint Rule
Section 106 Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager
Miracle Recreation Equipment, Inc
PO Box 420
Monett, MO 65708
(800) 523-4202

The product models covered by this certificate were manufactured on 09/03/08

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE	ACCREDITED
Applied Technical Services, Inc	Marietta, GA	12/05/08	yes
Scientific Control Laboratories	Chicago, IL	11/13/08	yes
Scientific Control Laboratories	Chicago, IL	12/18/08	yes
Specialized Technology Resource	Kwai Chung, NT	11/21/08	yes
St. Louis Testing Laboratories,	St. Louis, MO	12/01/08	yes
St. Louis Testing Laboratories,	St. Louis, MO	03/16/09	yes