

General Certificate of CPSIA Compliance

Customer & Ship To Address:

WHITACRE INSTALLATION INC
2608 WEST KENSOHA
BROKEN ARROW, OK 74012
Order Number:611665

The following product models are covered by this certificate:

715158FG	92" POST-CORNER 2'6 DECK FG
715161FG	92" POST-CORNER 3' DECK FG
715164FG	92" POST-2'6 TO 3' DECK RH FG
715171FG	102" POST-2'TO 2'6-3'-3'6 DECK RH FG
715174FG	92" POST-2' TO 2'6 TRANS DECK RH FG
715178FG	124" POST-CORNER 4'DECK,ROOF,IMAG-LH FG
715155FG	80" POST-TRANSFER PLATFORM LH FG
715181FG	124" POST-CORNER 4'DECK,ROOF,IMAG-RH FG
715208FG	102"POST-2'TO 3'6 DECK LH FG
715210FG	124"POST-3'6 TO 4'DECK LH, ROOF FG
715212FG	124"POST-3'TO 3'6-4'DECK RH,ROOF FG
715037BU	HANDRAIL-ECH TRANSFER STEP LOOSE FILL BU
715038BU	HANDRAIL-ECH TRANSFR PLATFORM-LOOS FIL BU
715041FG	ANCHOR-TRANSFER PLATFORM-LOOSE FILL FG
715034FG	ANCHOR-ECH SLIDE LOOSE FILL FG
715153FG	LEG-ECH GROOVE SLIDE W/LOOSE FILL FG
715206BU	HANDRAIL-HONEYCOMB CLIMBER-LOOSE FILL BU
715206BU	HANDRAIL-HONEYCOMB CLIMBER-LOOSE FILL BU

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101	Lead Paint Rule
Section 106	Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager
Miracle Recreation Equipment, Inc
PO Box 420
Monett, MO 65708

(800) 523-4202

The product models covered by this certificate were manufactured on 04/30/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE	ACCREDITED
Scientific Control Laboratories	Chicago, IL	11/13/08	yes
Scientific Control Laboratories	Chicago, IL	12/18/08	yes
St. Louis Testing Laboratories,	St. Louis, MO	12/01/08	yes