

General Certificate of CPSIA Compliance

Customer & Ship To Address:

ORTCO, INC.
2163 N. GLASSELL
ORANGE, CA 92865
Order Number:612348

The following product models are covered by this certificate:

R261408 BUSHING FOR MULTI PONDO-REPAIR KIT
985771BU EXIT SECTION 30" DIA TUBE W/INSERTS BU

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101 Lead Paint Rule
Section 106 Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager
Miracle Recreation Equipment, Inc
PO Box 420
Monett, MO 65708
(800) 523-4202

The product models covered by this certificate were manufactured on 04/30/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE	ACCREDITED
-----	-----	-----	-----
Eurofins Miljo A/S	Galten, SW	01/14/09	yes