

General Certificate of CPSIA Compliance

Customer & Ship To Address:

CITY OF RUSTON
PARKS & RECREATION
RUSTON, LA 71270
Order Number:612415

The following product models are covered by this certificate:

9897-1S9	BLEACHER 4 ROW GALV/ANOD ALUM/GALV
9897-2S9	BLEACHER 4 ROW GALV/PC ALUM/GALV
9897-2S9	BLEACHER 4 ROW GALV/PC ALUM/GALV
9897-2S9	BLEACHER 4 ROW GALV/PC ALUM/GALV
9897-2S9	BLEACHER 4 ROW GALV/PC ALUM/GALV

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101	Lead Paint Rule
Section 106	Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager
Miracle Recreation Equipment, Inc
PO Box 420
Monett, MO 65708
(800) 523-4202

The product models covered by this certificate were manufactured on 04/17/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB

LOCATION

TEST DATE ACCREDITED

-