

General Certificate of CPSIA Compliance

Customer & Ship To Address:

ALSALOR CORPORATION  
801 FARM ROAD 2035  
MONETT, MO 65708  
Order Number:612761

The following product models are covered by this certificate:

990890                      FLEX AXLE

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101      Lead Paint Rule  
Section 106      Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager  
Miracle Recreation Equipment, Inc  
PO Box 420  
Monett, MO 65708  
(800) 523-4202

The product models covered by this certificate were manufactured on 04/20/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE ACCREDITED
-----		
-		