

General Certificate of CPSIA Compliance

Customer & Ship To Address:

CITY OF CHANDLER  
4500 S. BASHA RD.  
CHANDLER, AZ 85248  
Order Number:612845

The following product models are covered by this certificate:

984118DB	PLATFORM CYCLONE DRILLED DB
103538YW	PLUG ROCKITE 2 1/2" YW
103543YW	PLUG ROCKITE 4" YW
713017DB	POST CAP 5" DIA DB

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101	Lead Paint Rule
Section 106	Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager  
Miracle Recreation Equipment, Inc  
PO Box 420  
Monett, MO 65708  
(800) 523-4202

The product models covered by this certificate were manufactured on 04/29/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE	ACCREDITED
St. Louis Testing Laboratories,	St. Louis, MO	12/01/08	yes