

General Certificate of CPSIA Compliance

Customer & Ship To Address:

LAGUNA NIGUEL REGIONAL PK  
28241 LA PAZ ROAD  
LAGUNA NIGUEL, CA 92677  
Order Number:613646

The following product models are covered by this certificate:

R261408                    BUSHING FOR MULTI PONDO-REPAIR KIT  
299                        TOT SEAT 360 DEG W/CLEVIS

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101            Lead Paint Rule  
Section 106            Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager  
Miracle Recreation Equipment, Inc  
PO Box 420  
Monett, MO 65708  
(800) 523-4202

The product models covered by this certificate were manufactured on 05/19/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE	ACCREDITED
-----	-----	-----	-----
Eurofins Miljo A/S	Galten, SW	01/14/09	yes