

General Certificate of CPSIA Compliance

Customer & Ship To Address:

CORPUS CHRISTI I.S.D.
FACILITIES & OPERATIONS
CORPUS CHRISTI, TX 78415
Order Number:613656

The following product models are covered by this certificate:

985954	BACK-UP FLANGE CYCLONE SLIDE ZINC PLTD
110066	NUT 3/8-16 HEX 18-8 SS CADMIUM PLATED
984116DB	1/2 TURN SECT CYCLONE DRILLED ROY
984118YW	PLATFORM CYCLONE DRILLED YW
104227	BOLT 3/8-16 X 1 3/4 HEX HD 18-8 SS
117005	WASHER 3/8 X 1 O.D. FLAT 18-8 SS

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101	Lead Paint Rule
Section 106	Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager
Miracle Recreation Equipment, Inc
PO Box 420
Monett, MO 65708
(800) 523-4202

The product models covered by this certificate were manufactured on 05/29/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE ACCREDITED
-----	-----	-----
-		