

General Certificate of CPSIA Compliance

Customer & Ship To Address:

CANTON TOWNSHIP
1150 S. CANTON CTR RD
CANTON, MI 48188
Order Number:613937

The following product models are covered by this certificate:

22136018	DISK, 6 HOLE LOW FLOW, 3.25 OD X .5 THK
22140001	BALL, .870 DIA W/.19 DIA HOLE, BRASS
22160013	NOZZLE, 1-1/2", 3 HOLES
30002008	NOZZLE ASSY, LOW FLOW FULL CONE

Each of these products is in compliance with the following sections of the Consumer Product Safety Improvement Act of 2008 (CPSIA):

Section 101	Lead Paint Rule
Section 106	Toy Safety Standards ASTM-F963

As the manufacturer/importer, Miracle Recreation Equipment, Inc located at 878 East Highway 60, Monett, MO, certifies the compliance of these products to the aforementioned sections of the CPSIA.

For additional information about actual test results, contact:

Quality Assurance Manager
Miracle Recreation Equipment, Inc
PO Box 420
Monett, MO 65708
(800) 523-4202

The product models covered by this certificate were manufactured on 06/03/09

Relevant testing for this Certificate of CPSIA Conformance was performed as follows.

LAB	LOCATION	TEST DATE ACCREDITED

-		